

## Service Bulletin

BKSB-1047 Issue Date 1/30/2017



Added the ability to have encryption settings for unit calls

## **Bug Fixes**

#### General:

Fixed "garbled" encrypted audio at the beginning/end of RX

Fixed no error tone or message while changing secure TX mode on a non-selectable channel

Fixed Voice Encoding Ignored while on a Trunking Channel

Added "Vote Scan" enable to the persistent setting length

Fixed transmit clear when radio is set to secure transmit mode

Fixed condition where the RX audio is not coming from the speaker when a qualified signal is received

Fixed file system error on power-up

Fixed the ability to toggle surveillance via the menu when surveillance mode is strapped to a channel

Fixed "audio squawk" when using button combination when zeroizing keys

Fixed timeout occurrence when RES write and "Configuring Radio" is being displayed Fixed unit call secure setting to not be selectable if strapped to "clear" or "secure" setting

Fixed NAC code programming while in the keypad programming menu



# Service Bulletin BKSB-1047



# Service Bulletin

BKSB-1047 Issue Date 1/30/2017



### **RES Software Update (Also see Service Bulletin BKSB-1048)**

**RES** is a new radio editor that is replacing NeoVision. RES Ver. 5.5.0 will read "code plugs" that were generated with firmware version 5.0.0 or later. If a code plug was generated with firmware Ver. 5.0.0 or later, then the code plug will be updated to Ver. 5.5.0 format when read.

Customers with a registered copy of the radio editor can download the latest release from the service section of relm.com by entering a valid serial number on the Software Update page. http://www.relmservice.com/software/update.asp

Authorized customers can download the updated version by logging in prior to navigating to the software section of the website.

The latest revision may also be purchased from your RELM/BK Radio dealer or directly from RELM Wireless at (800) 821-2900