



7100 Technology Drive
West Melbourne, FL 32904
1-800-422-6281

Service Bulletin

BKSB-1055

Issue Date: 5/15/2019



Issue: In unforeseen cases, firmware version 5.6.0a causes issues with operation and cloning of both portable and mobile radios.

Importance: Downloading the radios back to Firmware version 5.5.0F enables a stable platform for both portable and mobile radios.

Affected Models: Radios updated to firmware 5.6.0a

Recommended Action: Download radios back to Firmware 5.5.0F and convert radio files to RES version 5.5.3

In unforeseen cases, Firmware version 5.6.0a