



7100 Technology Drive
West Melbourne, FL 32904
1-800-422-6281

Service Bulletin

BKSB-1066

Issue Date: 4/15/2021



Issue: In some cases, if the PTT is pressed just after the boot-
the display is present, the transmitter will lock-up.

Importance: High

Affected Models: KAA0660 (Remote Control Head), and KAA0670 (Handheld Control Head).

Recommended Action: Update unit with firmware version 5.5.0q.

The -In- can be downloaded from BK Technologies, Inc. website
at: https://bktechnologies.com/service-portal/products/BK_KAA0733

Note: The release notes are included with the firmware download.

The release notes can be downloaded from BK Technologies, Inc. website at: [Release Notes](#)

Radio Firmware Update

Parts and Equipment Requirements:

1-