



Issue: RP Series belt-clips breaking

Affected Models: RP16 Series, RP99 Series, RP3000 Series and  
RP3600 Series.

Recommended Action: Provide a more robust belt-clip and unify belt-clip  
part numbers. RELM will provide two more robust belt-clips.