Service Bulletin

BKSB-1048
Issue Date 1/30/2017

Issue: Software Update – KAA0733 RES (Radio Editing Software) Ver. 5.5.0
    (Note: replaces Radio Editor NeoVision KAA0732/735)

Importance: Required if KNG Firmware Version is 5.5.0 or later

Affected Models: KNG-Pxxx, KNG2-Pxxx, KNG-Mxxx

Recommended Action: Update as required. The features and fixes are listed below.

NOTE: THIS BULLETIN DOES NOT APPLY TO <u>KNG-S</u> MODELS

Radio Editing Software Update
Note: Starting with Firmware Release 5.5.0, NeoVision will no longer be supported, instead the new editor, RES will take its place. The compatible RES (Radio Editing Software) version is 5.5.0.
Customers with a registered copy of the previous editor, NeoVision, will be able to download the newest editor from the service section of relm.com by entering a valid serial number on the Software Update page.
http://www.relmservice.com/products/
Authorized customers can download the new radio editor, RES, by logging in prior to navigating to the software section of the website.
The new radio editor, RES, may also be pu3(iB78(l)d886or)8.832(,)-7.62(R)4.88b.62)]TJ0.09i8.792(e.2 Tw ( )TJ