



7100 Technology Drive
West Melbourne, FL 32904
1-800-422-6281

Service Bulletin

BKSB-1027
Issue Date 05-27-2009

Issue:6281IsstM



7100 Technology Drive
West Melbourne, FL 32904
1-800-422-6281

Service Bulletin

BKSB-1027
Issue Date 05-27-2009

Procedure:

- 1) Verify the radio firmware revision installed in your DPH by pressing and holding the following buttons on the keypad:
 - a) “1” for Core code – current revision: