



7100 Technology Drive

Service Bulletin

BKSB-1028

Issue Date 08-06-2009



7100 Technology Drive
West Melbourne, FL 32904
1-800-422-6281

Service Bulletin

BKSB-1028
Issue Date 08-06-2009

The current Core revision is 3AE1717A

NOTE: The KNG Field Update Program automatically checks the installed firmware revision and only installs the update if required.

- 2) Download, install and run the KNG Field Update Program (*KNG_Update_0809.zip*) from the service section of the www.relm.com.

Firmware Page: http://www.relm.com/Sections/Service/BK_Firm.asp