



7100 Technology Drive
West Melbourne, FL 32904
1-800-422-6281

Service Bulletin

BKSB-1040
Issue Date 2/3/15

NOTE: THIS BULLETIN APPLIES TO THE KNG-M SERIES AND KAA0660

Issue: The key ring on Hirose connector of the KAA0290 and KAA0276 is breaking.

Importance: Corrective action



7100 Technology Drive
West Melbourne, FL 32904
1-800-422-6281

Service Bulletin

BKSB-1040
Issue Date 2/3/15

INCORRECT:



CORRECT:

