



Service Bulletin

BKSB-1042



7100 Technology Drive
West Melbourne, FL 32904
1-800-422-6281

Service Bulletin

BKSB-1042
Issue Date 6/3/2016



Mobile:



7100 Technology Drive
West Melbourne, FL 32904
1-800-422-6281

Service Bulletin

BKSB-1042
Issue Date 6/3/2016



- 2) Download and install the KNG Field Update 5.4.0b for your portable, mobile, remote mount control head or handheld control head from the service section of the www.relm.com.

Shortcut: http://www.relmservice.com/products/BK_Digital.asp

Software Update

NOTE: Radios with software version 5.4.0b may require an updated Neovision radio editor. The compatible Neovision radio editor version is 2.4.0

Customers with a registered copy of the radio editor can download the latest release from the service section of [relm.com](http://www.relm.com) by entering a valid serial number on the Software Update page. <http://www.relmservice.com/software/update.asp>

Authorized customers can download the updated version by logging in prior to navigating to the software section of the website.

The latest revision may also be purchased from your RELM/BK Radio dealer or directly from RELM Wireless at (800) 821-2900