



7100 Technology Drive  
West Melbourne, FL 32904  
1-800-422-6281



BKSB-1050  
Issue Date 6/7/2017



Issue: Destination clone errors with firmware 5.5.0 and older

Importance: Resolves clone errors with older firmware

Affected Models: KNG-Pxxx, KNG2-Pxxx, KNG-Mxxx

Recommended Action: Follow