

Service Bulletin

BKSB-1051

Issue Date 6/7/2017

7100 Technology Drive
West Melbourne, FL 32904
1-800-422-6281

Issue: Firmware inadvertently loaded into the wrong radio

Importance: