



7100 Technology Drive  
West Melbourne, FL 32904  
1-800-422-6281

# Service Bulletin

BKSB-1074a

Issue Date: 03/31/2022



## Issue:

BK Technologies has identified a potential issue which could result in a radio not powering up when the radio operator places the switch into the on position. This condition has only been noted during the power up sequence and has not been noted after the radio has gone through a successf