



7100 Technology Drive
 West Melbourne, FL 32904
 1-800-422-6281

Service Bulletin

BKSB-1076

Issue Date: 5/16/2022



Issue: Resolves the problem of having update BT files in the BT folder when updating the BT software. BT010000002

Importance: High

Affected Models: BKR5000 Series