

Service Bulletin

BKSB-1033 Issue Date 08-9-2012

7100 Technology Drive West Melbourne, FL 32904 1-800-422-6281

Type: Firmware and PC Radio Editor Updates

**Issue:** Implementation of added features and functions.

**Affected Models:** KNG digital portables, mobiles and remote heads.

**Recommended Action:** Update radio firmware and software.

Added/Updated radio features:

## Channel Number + Zone Label

Adds display line to show selected channel number and selected zone label.

-----

### **Home Channel**

Adds assignable Home Channel button or menu item.

## **Dual Mode Scan List Selection**

Adds user selectablity to dual mode scan list.

## Digital DTMF decode

Allows DTMF paging in digital operation.

### **Vote Scan List**

Allows user selectable vote scan channels on radios with optional vote scan.

\_\_\_\_\_

## **Mobile GPS Support**

Adds support for optional mobile radio GPS features.

#### **Enhanced Control Lock**

Designate which items are disabled when Control Lock is selected.

## Default Squelch

Changed preset squelch value to allow audio at lower signal level.

## Wide Area Trunking

Adds wide area single site support.

# **Firmware Update**

# **Parts and Equipment Requirements:**

- 1- KAA0710 Programming Cable
- 1- Firmware Update from RELM.com

### Procedure:

- Verify the radio firmware revision installed in your KNG. Select "Versions" from the radio menu. Update radios who's software version is less than 4.5.0.
- 2) Download and install the KNG Field Update 4.5.0 for your portable, mobile or remote mount control head from the service section of the www.relm.com.

Shortcut: http://www.relmservice.com/products/BK Digital.asp

# **Software Update**

NOTE: Radios with software version 4.5.0 may require an updated Neovision radio editor. The compatible Neovision radio editor version is 1.4.19

Customers with a registered copy of the radio editor can download the latest release from the service section of relm.com by entering a valid serial number on the Software Update page. <a href="http://www.relmservice.com/software/update.asp">http://www.relmservice.com/software/update.asp</a>

Authorized customers can download the updated version by logging in prior to navigating to the software section of the website.

The latest revision may also available be purchased from your RELM/BK Radio dealer or directly from RELM Wireless by at (800) 821-2900