



Service Bulletin

BKSB-1005
Issue Date 08-15-01

Issue: Display does not light when switched on in low ambient light.

Affected Models: GPH5992X Dash mount models serial number less than 0112000.

Recommended Action: