



Service Bulletin

BKSB-1019

Issue Date 11-12-03

Issue: DPH Firmware update to allow user selectable NAC and Code Guard between analog, digital and mixed mode channels.

Affected Models: All DPH models

Recommended Action: Upgrade firmware to Rev. 2F2383C1. It is recommended by BK Radio