



7100 Technology Drive
West Melbourne, FL 32904
1-800-422-6281

Service Bulletin

BKSB-1070

Issue Date: 12/1/2021



Issue: Resolves potential cloning issues. Please see release notes.

Importance: High

Affected Models: All KNG-Pxxx, KNG2-Pxxx, KNG-